

## GLV ERRATA

### GLV\_BOB

1. Change Screw Terminals to a single Molex connector
2. Fix Fault Light transistor footprint.
3. Change R6&R7 to 2.2K
4. 100V supply relay footprint needs to be updated to have 2 connections due to the use of a double throw normally open relay.
5. Fix Screw hole location to align with the plate hole location