

## Fall 2018 Interconnect Errata

### Things to fix:

1. Solve strain relief on DT connectors.
2. Investigate upgrades for low voltage motor controller connector.
3. Determine if CAN actually needs shielding or if any multi-conductor cable will work.
4. Improve Cooling system cable management.
5. Increase labeling.
6. Improve communication during design phase.

### Things to do next semester:

1. Buy orange high voltage cables
2. Buy Amphenol Powerlok connectors (301 series, right angle, 70 mm<sup>2</sup>)
3. Manufacture low voltage TSV interconnect.