

Wiring diagram:

Name each block.

Use P for movable connectors.

Check the fuse at MC+.

Check HV & LV: there should be no cable between them.

Firmware:

Consider using drive led to indicate different situations when exiting DRIVE mode.

- (BP & drive_btn), (throttleimplausibility), (mc_active)