
## PACK OVERVIEW - ASSEMBLY 7 1 MAY 2014

REFERENCE TABLE			
REFERENCE DESIGNATOR	ASSEMBLY/PART NO	DESCRIPTION	QUANTITY
1	L1	PACK BASE PLATE	1
2		NEGATIVE SIDE CHARGING RELAY	1
3		8/32 0.5" SOCKET HEAD BOLTS	2
4	L5	PCB MOUNT BOARD	1
5		PACMAN BREAKOUT BOARD	1
6	TS81604200	SINGLE BOARD COMPUTER	1
7		4-40 x 3/4" LONG 3/16 HEX M/F STANDOFFS	8
8		4-40 x 3/8" PHILIPS HEAD BOLTS	8
9		#8x7/8 FLAT HEAD WOOD SCREW	3
	REFERENCE DESIGNATOR 1 2 3 4 5 6 7 8 9	REFERENCE DESIGNATORASSEMBLY/PART NO1L12	REFERENCE DESIGNATORASSEMBLY/PART NODESCRIPTION1L1PACK BASE PLATE2NEGATIVE SIDE CHARGING RELAY38/32 0.5" SOCKET HEAD BOLTS4L5PCB MOUNT BOARD5PACMAN BREAKOUT BOARD6TS81604200SINGLE BOARD COMPUTER74-40 x 3/4" LONG 3/16 HEX M/F STANDOFFS84-40 x 3/8" PHILIPS HEAD BOLTS



CONSTRUCTION NOTE: METAL STANDOFFS ASSEMBLED BY GLUING FEMALE SIDE UP AND MALE SIDE REMOVED

