

February 6th Meeting Agenda

- 1) Monday Team Reports
- 2) Photoresistor Model
 - a) Create a new team
 - i) Chiko
 - ii) Haki
 - iii) Tim
 - iv) Zheping
- 3) Gantt Chart
- 4) Power Board Review
 - a) Get part dimensions to AK so she can begin laying them out
 - b) Relay coils in parallel (they can't be in series)
 - c) Motors
 - i) One in series, one in parallel
 - d) Do not make both control panels true at the same time**
- 5) Questions or Concerns?