

ⓘ ⓘ ⓘ ⓘ	Motor Temperature: XXX F State Of Charge: XX % Current: XXX A	⌘ < ✓ > X v
------------------	---	-------------------

Press "Check" Button

ⓘ ⓘ ⓘ ⓘ	RECORDING Motor Temp: XXX F State Of Charge: XX % Current: XXX A	⌘ < ✓ > X v
------------------	---	-------------------

Press "X" Button

ⓘ ⓘ ⓘ ⓘ	Motor Temperature: XXX F State Of Charge: XX % Current: XXX A	⌘ < ✓ > X v
------------------	---	-------------------

Monitored value exceeds threshold

ⓘ ⓘ ⓘ ⓘ	CHECK ENGINE Motor Temperature: XXX F State Of Charge: XX % Current: XXX A	⌘ < ✓ > X v
------------------	---	-------------------