

VSCADA Errata

ECE 491 - Fall 2018

Latest Revision: 12/5/2018

Prepared by: 12/4/2018

Abstract

This document is intended for recording what we will mix for further design and our recommendation for later groups.

Table of Contents

Executive Summary	2
Errata	2

Executive Summary

Errata

- (1) More types of calibration method should be designed to fit in a look up table or log function.
- (2) Using WIFI connection to transmit data from VSCADA to other computer in real time.
- (3) A more specific error diagnosis for more types of error conditions
- (4) More functions and test on the dashboard display in front of the driver
- (5) More test on determine the data has been missed or not
- (6) Add error handling function on dashboard display
- (7) Further improvement on the efficiency and reduce possible lag